

# SKAGWAY AIRPORT

## **Contents:**

- A Pavement Strength Form showing project history, latest Pavement Condition Index (PCI) data, pavement strength ratings (if available) and other useful information
- A Pavement Condition Survey – PCI Sample Unit Layout Plan
- PCI maps showing as-measured and predicted pavement conditions
- Age map showing pavement age as of January 2003
- A Branch PCI Condition Report
- A Section PCI Condition Report

## **Airport Information:**

- Location: Northeast part of Southeastern (Panhandle) Alaska, west of the town of Skagway.  
The runway was relocated and constructed west of the former runway and the entire airport reconstructed and completed in 2000.
- District: Southeast
- Airport Manager: Keith Knorr
- District Maintenance Manager: Gary Hayden
- Pavement Surface: Asphalt Concrete
- Last Pavement Construction: 2000
- Pavement layout: Runway 2-20, 8 taxiways and 3 aprons
- Design Aircraft: General Aviation
- 2001 Enplanements: 10,168
- Airport Class: Primary
- Last pavement condition survey: 2002
- Next planned pavement condition survey: 2005
- 2001 reported pavement maintenance and/or changed conditions: No report
- Recommendations: See PCI maps